

COPPER ASSEMBLY PART NUMBERS

F
 1 2 3 4 5 6 7 8 9 10 11

1 WIRING PATTERN

A = 568A

B = 568B

X = CROSSOVER

(CAT6 STANDARD WIRING PATTERN WILL BE
GIGABIT CROSSOVER)

2 CABLE TYPE

0 = STRANDED RISER

P = SOLID PLENUM

L = SOLID RISER

S = SOLID SHIELDED NON-PLENUM

H = STRANDED SHIELDED NON-PLENUM D = SOLID SHIELDED PLENUM

3 BOOTS

0 = NO BOOTS

S = SNAGLESS BOOTS (SAME COLOR AS CABLE)

P = PANDUIT SNAGLESS CONNECTOR

G = SNAGLESS BOOT (CUSTOM COLOR CONFIGURATION)

4 0 = RJ45-RJ45

3 = RJ45- RJ45 SHIELDED

1 = RJ45-110

4 = RJ45 SHIELDED - RJ45 SHIELDED

2 = 110 - 110

(SHIELDED RJ45'S ONLY USED WITH SHIELDED CABLE)

5 CABLE SPEED

Z = CAT5E

6 = CAT6

6 1 = 4 PAIR CABLE

2 = 2 PAIR CABLE

7, 8, 9 LENGTH

10 F = Feet

M = Meters

11 COLOR

A=GRAY

G=GREEN

P=PURPLE

N=PINK

B=BLUE

K=BLACK

R=RED

Y=YELLOW

E=BEIGE

O=ORANGE

W=WHITE